

# REPORT OF INSPECTION IN ACCORDANCE WITH THE PARIS MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL <sup>\*)</sup>

## Reporting Authority:

- Aberdeen Marine Office  
- Marine House - Blaikies Quay - Aberdeen AB11 5EZ  
- Phone: +44 (0)1224 597903  
- Fax: +44 (0)1224 571920  
- E-mail:

## copy to:

- master  
- head office  
- PSCO

## if ship is detained, copy to:

- flag state

## SHIP DETAINED

### SHIP PARTICULARS

<p><b>1 Name of ship:</b> ADINATH ONE</p> <p><b>3 Type of Ship:</b> Offshore supply</p> <p><b>5 IMO number:</b> 9019286</p> <p><b>7 Date keel laid / major conversion commenced:</b> 10/04/1991</p>	<p><b>2 Flag of ship:</b> India</p> <p><b>4 Call sign:</b> AVOJ</p> <p><b>6 Gross tonnage:</b> 2145</p> <p><b>8 Deadweight (where applicable):</b></p>
---	--

**9a. Classification society(ies) responsible for issuance of class certificates:**

DNV Det Norske Veritas **Issued on:** 21/10/2011 **Expired on:** 28/04/2012

**9b. Recognised Organisation(s) responsible for issuance of certificates on behalf of the flag State:**

IRS Indian Register of Shipping

**10. Full particulars of company (Identical to particulars as in the ISM DoC <sup>\*\*</sup>)**

**IMO number:** 5060206 **Name:** ABS Marine **Address:** **City:** **Country:**  
Services Pvt Ltd

**11. Name and address of charterer (Only ships carrying liquid or solid cargoes in bulk, pref .1st charterer record.)**

**12. Name and signature of master to certify that the information under 11 (and under 10 if <sup>\*\*</sup> is applicable) is correct:**

**Name:** \_\_\_\_\_ **Signature:** \_\_\_\_\_

### INSPECTION PARTICULARS <sup>\*\*\*</sup>

**13a Date of first visit:** 26/10/2011 **13b. Date of final report:** 01/11/2011

**14 Place of inspection:** Aberdeen

**15 If the vessel is detained: Date of issue of Detention Notice:** 26/10/2011

**16. Type of Inspection:** More detailed inspection

**(C).I.C:** Structural Safety and International Convention on Load Lines

<sup>\*)</sup> This inspection report has been issued solely for the purpose of informing the master and other port States that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as seaworthiness certificate in excess of the certificates the ship is

<sup>\*\*</sup>) Non-ISM Ships: Master to supply and sign under 12. for correct full particulars of the company.

<sup>\*\*\*</sup>) Masters, ships owners and/or Operators are advised that detailed information on the inspection may be subject to publication (www.parismou.org).

Name of Ship: ADINATH ONE

IMO Number: 9019286

Date of inspection: 01/11/2011

**17 Operational Controls (if any)**

- Other
- Damage Control drill
- SMPEP drill
- Abandon ship drill
- Fire drill
- SOPEP drill

**18. Areas Inspected**

- Accommodation and galley
- Ballast tanks - from manhole
- Cargo holds / tanks
- Navigation bridge
- Passenger spaces
- Ballast tanks - internal
- Vehicle deck
- Engine room
- Outside decks and forecastle
- Steering room

Name of Ship: ADINATH ONE

IMO Number: 9019286

Date of inspection: 01/11/2011

**19. Relevant Certificate(s)**

**e. Information on last intermediate or annual survey**

Nr.	a. Title	b. Issuing	c. Date	d. Date	Date	Surveying	Country
	Bunker Oil Pollution Damage	United Kingdom	25/10/2011	20/10/2012			
2	Cargo Ship Safety Construction	R.O IRS	26/10/2011	31/03/2012			
3	Cargo Ship Safety Equipment	R.O IRS	26/10/2011	31/03/2012			
4	Cargo Ship Safety Radio	R.O IRS	26/10/2011	31/03/2012			
5	Document of Compliance	Flag India	24/03/2010	28/03/2012	21/04/2011	Flag India	India
6	Document of Compliance Dangerous Goods	R.O IRS	26/10/2011	31/03/2012			
7	International Air Pollution Prevention	R.O IRS	26/10/2011	31/03/2012			
8	International Anti-Fouling System	R.O IRS	26/10/2011	31/03/2012			
9	International Oil Pollution Prevention (IOPP)	R.O IRS	26/10/2011	31/03/2012			
10	International Pollution Prevention (NLS in Bulk)	R.O IRS	26/10/2011	31/03/2012			
11	International Sewage Pollution Prevention	R.O IRS	26/10/2011	31/03/2012			
12	International Ship Security	R.O IRS	26/10/2011	30/04/2012			
13	Load Line	R.O IRS	26/10/2011	31/03/2012			
14	Minimum Safe Manning Document	Flag India	19/09/2011				
15	Safety Management Certificate	R.O IRS	26/10/2011	31/01/2012			

**20 Ship related inspection action taken**

113 - Inspection suspended

**21 Deficiencies**

No

Yes (see attached FORM B)

Name of Ship: ADINATH ONE  
Date of inspection: 01/11/2011

IMO Number: 9019286

**22. Supporting Documentation**

No

Yes (see annex)

**PORT STATE PARTICULARS**

District Office                      Aberdeen Marine Office  
Address                                Marine House - Blaikies Quay - Aberdeen AB11 5EZ  
Telephone                            +44 (0)1224 597903  
Telefax                                +44 (0)1224 571920  
E-mail  
Name (duly authorized PSCO  
of reporting authority)            XXXXXXXXXXXXX  
Signature                             \_\_\_\_\_

This report must be retained on board for a period of at least two years and must be available for consultation by the Port State Control Officers at all times.

## REPORT OF INSPECTION IN ACCORDANCE WITH THE PARIS MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL

## Reporting Authority:

- Aberdeen Marine Office
- Marine House - Blaikies Quay - Aberdeen AB11 5EZ
- Phone: +44 (0)1224 597903
- Fax: +44 (0)1224 571920
- E-mail:

## copy to:

- master
  - head office
  - PSCO
- if ship is detained, copy to:
- flag state
  - recognised organisation, if applicable

Name of Ship: ADINATH ONE

IMO Number: 9019286

Date of final report: 01/11/2011

Place of inspection: Aberdeen

### SHIP DETAINED

### DEFICIENCIES FOUND AND FOLLOW UP ACTIONS <sup>\*\*\*)</sup>

Nr.	Defective Item	Nature of defect <sup>1)</sup>	Convention ref. <sup>2)</sup>	Ground for detention	Action taken	Additional Comments	RO resp. <sup>2)</sup>
1	09111-Sickbay	Not as required	C147 and P147: Accommodation, recreational facilities, food and catering	<input type="checkbox"/>	99 - Master instructed to ...	HOSPITAL REQUIRED FOR NUMBER OF CREW IN EXCESS 15	<input type="checkbox"/>
2	11129-Operational readiness of lifesaving appliances	Not as required		<input type="checkbox"/>	17 - To be rectified before departure	SECURING STROPS FOR RESCUE BOAT TO FREE OFF	<input type="checkbox"/>
3	03102-Freeboard marks	Not as required		<input type="checkbox"/>	99 - Master instructed to ...	IR MARKING NOT PERMANENT	<input type="checkbox"/>
4	02120-Marking of IMO number	Not as required	SOLAS ch. XI-1	<input type="checkbox"/>	99 - Master instructed to ...	NOT PERMANENTLY MARKED	<input type="checkbox"/>
5	01134-Other (certificates)	Other	SOLAS ch. I	<input type="checkbox"/>	99 - Master instructed to ...	MARKING OF SHIPS NAME, PORT OF REGISTRY NOT PERMANENT (REGISTRY AND TONNAGE CERTIFICATION).	<input type="checkbox"/>
6	07115-Fire-dampers	Not as required	SOLAS ch. II-2	<input type="checkbox"/>	16 - To be rectified within 14 days	STARBOARD ENGINE ROOM	<input type="checkbox"/>
7	07110-Fire fighting equipment and appliances	Not properly maintained	SOLAS ch. II-2 - SOLAS CH II-2	<input checked="" type="checkbox"/>	10 - Rectified	FIRE HYDRANT COUPLING LEAKING FROM THE SEAL	<input type="checkbox"/>
8	09210-Machinery	Unsafe	C147 and P147: Health	<input checked="" type="checkbox"/>	10 - Rectified	OIL LEAKAGE FROM CRANK CASE	<input type="checkbox"/>

\*\*\*) Masters, Ship owners and/or Operators are advised that detailed information on the inspection may be subject to publication ([www.parismou.org](http://www.parismou.org))

<sup>1)</sup> This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out and all deficiencies are rectified before an application for re-inspection is made.

<sup>2)</sup> To be completed in the event of a detention.(for non-convention ships <500 GT for reference only)

Name of Ship: ADINATH ONE

IMO Number: 9019286

Date of final report: 01/11/2011

Place of inspection: Aberdeen

protection, medical care,  
welfare & social security -  
SOLAS CH II - 1BREATHER OF A/E (S) OIL BEING  
COLLECTED UNDER THE ENGINES IN A  
PLASTIC CONTAINER

9	02105-Steering gear	Not properly maintained	SOLAS ch. II-1 Parts C, D, E, F - SOLAS CH II - 1	<input checked="" type="checkbox"/>	10 - Rectified	STEERING GEAR (STBD) HYDRAULIC PUMP NO 4 LEAKING FROM GLAND	<input type="checkbox"/>
10	14105-Pumping, piping and discharge arrangements	Not as required	MARPOL Annex I - MARPOL AN 1	<input checked="" type="checkbox"/>	10 - Rectified	UNAPPROVED PIPING ATTACHED TO SLUDGE PUMP	<input type="checkbox"/>
11	01124-International Air Pollution Cert.	Missing	MARPOL Annex VI	<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>
12	01122-International ship security certificate	Missing		<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>
13	01119-International Sewage Pollution Prevention Cert.	Missing	MARPOL Annex IV	<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>
14	01117-International Oil Pollution Prevention (IOPP)	Missing	MARPOL Annex I	<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>
15	01104-Cargo Ship Safety Radio (including exemption)	Missing	SOLAS ch. I	<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>
16	01102-Cargo Ship Safety Construction (including exempt.)	Missing	SOLAS ch. I	<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>
17	01108-Load Lines (including Exemption)	Missing	Load Lines	<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>
18	01107-Safety Management Certificate (SMC/ ISM)	Missing		<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>
19	01101-Cargo Ship Safety Equipment (including exemption)	Missing	SOLAS ch. I	<input type="checkbox"/>	10 - Rectified		<input type="checkbox"/>

**Name of Ship:** ADINATH ONE

**IMO Number:** 9019286

**Date of final report:** 01/11/2011

**Place of inspection:** Aberdeen

**Name (duly authorized PSCO of reporting authority):**

XXXXXXXXXXXX

**Signature:**

\_\_\_\_\_